


PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS

CASE HISTORY 025 - LARGE PUMP REPAIR



1) **Problem:**

Large Worthington salt water pump packing sleeve had excessive leakage.

2) **Circumstances prior to failure:**

Customer scheduled repair contractor to provide removal, repair and reinstallation.

3) **Pumpcoat Solution**

Pumpcoat coordinated contractors who removed the pump, rebuilt and reinstalled the unit.

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.



PO Box 1109
Mashpee, MA 02649

www.pumpcoat.com

Contact:

Cpg1parts@aol.com (email)

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)