


# PUMPCOAT

## THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS

### CASE HISTORY 027 - CONDENSER WATER BOX REPAIR



1) **Problem:**

Customer had hole in condenser water box.



2) **Circumstances prior to failure:**

Corrosion weakened the metal and customer needle-gunned a hole in condenser water box.

3) **Pumpcoat Solution.**

Pumpcoat coating technician repaired hole by grit blasting, applying paste grade epoxy to fill the corroded area, and then a top coat to seal and waterproof. Patch was reinforced with polyester cloth. Patch has been working for 5 years.

---

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND  
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK  
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

### Pumpcoat, Inc.

PO Box 1109  
Mashpee, MA 02649  
sales@pumpcoat.com

www.pumpcoat.com  
1-888-312-7278 (toll-free)  
1-508-540-5878 (phone)  
1-508-457-1052 (fax)