

PUMPCOAT

THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS

CASE HISTORY 031 - HEAT EXCHANGER DIVISION PLATE COATING



1) **Problem:**

Division bars on heat exchanger cover were corroded.



2) **Circumstances prior to failure:**

Customer experiencing leakage where the division plate bars had corroded.

3) **Pumpcoat Solution**

Pumpcoat grit blasted the cover and repair welded the division bars. Piece was then epoxy coated for corrosion resistance.



OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

sales@pumpcoat.com

www.pumpcoat.com

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)