


# PUMPCOAT

## THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS

### CASE HISTORY 033 - EPOXY COATED & CUSTOM PUMP BASES



1) **Problem:**

Trash burning power plant had excessive corrosion on several pump bases.

2) **Circumstances prior to failure:**

Customer had fish pumps in salt water service. The pump bases had suffered corrosion & oxidation.

3) **Pumpcoat Solution**

Pumpcoat mobilized to customers site to blast, repair damage, and epoxy coat the pump bases. This repaired & prevented further damage and the coating offered extra wear resistance for the future. In cases of extreme damage or an existing base, Pumpcoat also has the capability of custom manufacturing pump bases to specifications.



---

OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND  
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK  
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

### Pumpcoat, Inc.

PO Box 1109  
Mashpee, MA 02649  
sales@pumpcoat.com

www.pumpcoat.com  
1-888-312-7278 (toll-free)  
1-508-540-5878 (phone)  
1-508-457-1052 (fax)