



# PUMPCOAT

## THE RIGHT SOLUTION TO YOUR PUMP AND COATING PROBLEMS

### CASE HISTORY 009 - TRAVELING WATER SCREEN REPAIR



1) **Problem:**

Traveling Water Screen frame rusts out.

2) **Circumstances prior to failure:**

Customer welds and strengthens new traveling water screen frame prior to installation. Heat from welding destroys factory coating.

3) **Pumpcoat Solution**

Pumpcoat provides qualified coating people to identify coating repair areas, grind and prepare those areas and coat with two coats of ceramic epoxy



OUR MISSION IS TO PROVIDE HIGHLY TECHNICAL AND  
RELIABLE SERVICE THROUGH OUR ESTABLISHED NETWORK  
OF AFFILIATED VENDORS AND STRATEGIC PARTNERS.

### Pumpcoat, Inc.

PO Box 1109

Mashpee, MA 02649

[sales@pumpcoat.com](mailto:sales@pumpcoat.com)

[www.pumpcoat.com](http://www.pumpcoat.com)

1-888-312-7278 (toll-free)

1-508-540-5878 (phone)

1-508-457-1052 (fax)

~ WBE Certified ~